

**Exhibit A – Honda/Acura Vehicles Originally Equipped with  
*Alpha* Inflators**

| Make/Model    | Model Year | Recall  | VIN Range   | Manufacture Date   |
|---------------|------------|---------|---|--|
| Accord 2-Door | 2001       | 09V-259 | 1HGCG22561A000014 -<br>1HGCG22471A035443<br>1HGCG32571A000013 -<br>1HGCG325X1A032650  | 7/18/2000 -<br>8/3/2001<br>7/18/2000 -<br>7/30/2001  |
|               |            | 10V-041 | 1HGCG22501A014572 -<br>1HGCG22491A036691<br>1HGCG32701A018631 -<br>1HGCG32781A034267  | 1/15/2001 -<br>8/14/2001<br>3/21/2001 -<br>8/14/2001   |
|               |            | 11V-260 | 1HGCG22551A007875 -<br>1HGCG22461A036745<br>1HGCG32531A004530 -<br>1HGCG316X1A034375  | 11/6/2000 -<br>8/15/2001<br>11/4/2000 -<br>8/15/2001   |
| Accord 2-Door | 2002       | 09V-259 | 1HGCG22542A001082 -<br>1HGCG22562A010432<br>1HGCG32022A001110 -<br>1HGCG32502A008343  | 8/23/2001 -<br>11/14/2001<br>8/22/2001 -<br>11/16/2001   |
|               |            |         | 1HGCG22582A000145 -<br>1HGCG22502A032863<br>1HGCG32032A000001 -<br>1HGCG32132A030382  | 8/15/2001 -<br>6/28/2002<br>6/12/2001 -<br>6/28/2002   |
|               |            | 11V-260 | 1HGCG22562A000001 -<br>1HGCG22592A029461<br>1HGCG32052A000002 -<br>1HGCG32592A014528  | 8/15/2001 -<br>5/20/2002<br>8/8/2001 -<br>1/28/2002  |
| Accord 4-Door | 2001       | 09V-259 | 1HGCF85461A000202 -<br>1HGCF86601A146921<br>JHMCF85471C000002 -<br>JHMCF86421C000813<br>1HGCG16411A000014 -<br>1HGCG16511A087275<br>1HGCG56661A000017 -<br>1HGCG56621A148794<br>3HGCG56471G700001 -<br>3HGCG56461G700720<br>JHMC56421 C000015 -<br>JHMC56631C033252<br>1HGCG66521A000142 -<br>1HGCG665X1A148250 | 8/21/2000 -<br>7/20/2001<br>7/17/2000 -<br>6/26/2001<br>7/20/2000 -<br>7/31/2001<br>7/20/2000 -<br>7/27/2001<br>7/02/2001 -<br>8/9/2002<br>1/13/2001 -<br>7/3/2001<br>8/21/2000 -<br>7/26/2001 |

| Make/Model    | Model Year | Recall  | VIN Range  | Manufacture Date   |
|---------------|------------|---------|--|--|
|               |            |         | 3HGCG66571G700367 -<br>3HGCG66501G703840<br>JHMCG65561C000003 ~<br>JHMCG66001C027751   | 10/9/2000 -<br>3/09/2001<br>7/4/2000 -<br>7/3/2001   |
|               |            | 10V-041 | 1HGCG165X1A036051 -<br>1HGCG16501A087302<br>1HGCG56661A089569 -<br>1HGCG56481A149995<br>1HGCG66531A077974 -<br>1HGCG66581A149994<br>1HGCF86681A070199 -<br>1HGCF866X1A149454<br>JHMC86441C000750 -<br>JHMC86471C000824<br>JHMCG56401C032199 -<br>JHMCG56631C033283<br>JHMCG66051C026336 -<br>JHMCG66061C027821 | 1/15/2001 –<br>8/1/2001<br>3/19/2001 –<br>8/1/2001<br>2/26/2001 –<br>7/31/2001<br>2/6/2001 –<br>7/27/2001<br>6/11/2001 –<br>7/03/2001<br>5/28/2001 –<br>7/05/2001<br>5/16/2001 -<br>7/07/2001    |
|               |            | 11V-260 | JHMC864X1C000138 -<br>JHMC86411C000737<br>1HGCF86471A026466 -<br>1HGCF86661A148611<br>1HGCG16581A018745<br>1HGCG165X1A087257<br>JHMCG55431 C000011 -<br>JHMCG56621C032903<br>1HGCG56651A024471 -<br>1HGCG56471A149857<br>JHMCG65581C000004 -<br>JHMCG66001C027345<br>1HGCG66551A026010 -<br>1HGCG668X1A149232  | 8/23/2000 -<br>4/17/2001<br>10/30/2000 -<br>7/26/2001<br>10/27/2000<br>7/31/2001<br>7/6/2000 -<br>6/26/2001<br>10/27/2000 -<br>7/31/2001<br>7/6/2000 -<br>6/27/2001<br>10/27/2000 -<br>7/27/2001 |
| Accord 4-Door | 2002       | 09V-259 | 1HGCF86662A001089 -<br>1HGCF86662A054018<br>JHMC86402C000005 -<br>JHMC86462X000086<br>1HGCG16522A000985 -<br>1HGCG16542A037889<br>1HGCG56722A000607 -  | 8/11/2001 -<br>12/4/2001<br>7/26/2001 -<br>8/1/2001<br>8/2/2001 -<br>12/4/2001<br>7/31/2001 -  |

| Make/Model | Model Year | Recall  | VIN Range  | Manufacture Date  |
|------------|------------|---------|--|---|
|            |            |         | 1HGCG56442A056165<br>3HGCG56452G700001 -<br>3HGCG564X2G703704<br>JHMCG56782C000001 -<br>JHMCG56772C033281<br>3HGCG66572G7000001 -<br>3HGCG66532G703705<br>JHMCG66542C000145 -<br>JHMCG66032C028832   | 12/7/2001<br>8/17/2001 -<br>2/26/2002<br>6/11/2001 -<br>4/16/2002<br>8/13/2001 -<br>2/8/2002<br>7/5/2001 -<br>5/13/2002   |
|            |            | 10V-041 | 3HGCG56452G700001 -<br>3HGCG56402G706126<br>3HGCG66572G700001 -<br>3HGCG66502G705881<br>1HGCG16412A000001 -<br>1HGCG165X2A060304<br>1HGCG567X2A000001 -<br>1HGCG56402A156781<br>1HGCG66802A000314 -<br>1HGCG668X2A115079<br>1HGCF86662A000122 -<br>1HGCF86602A116108<br>JHMC85432C000001 -<br>JHMC86462C000492<br>JHMCG56442C000003 -<br>JHMCG56612C031498<br>JHMCG66522C000001 -<br>JHMCG66852C025436 | 8/17/2001 -<br>6/7/2002<br>8/13/2001 -<br>6/3/2002<br>7/31/2001 -<br>4/8/2002<br>5/10/2001 -<br>6/26/2002<br>7/31/2001 -<br>4/5/2002<br>7/31/2001 -<br>4/8/2002<br>7/26/2001 -<br>3/15/2002<br>7/4/2001 -<br>2/27/2002<br>7/4/2001 -<br>2/20/2002 |
|            |            | 11V-260 | JHMC86422C000117 -<br>JHMC85402C000490<br>1HGCF86692A001247 -<br>1HGCF86662A144494<br>1HGCG164X2A000031 -<br>1HGCG16582A069938<br>JHMCG56702C002387 -<br>JHMCG56632C030806<br>1HGCG56712A000002 -<br>1HGCG56652A140044<br>JHMCG66802C001867 -<br>JHMCG66542C025157   | 9/4/2001 -<br>2/7/2002<br>8/1/2001 -<br>6/3/2002<br>8/1/2001 -<br>5/30/2002<br>7/16/2001 -<br>2/11/2002<br>7/25/2001 -<br>5/17/2002<br>7/17/2001 -<br>2/8/2002  |

| Make/Model   | Model Year | Recall  | VIN Range   | Manufacture Date  |
|--------------|------------|---------|---|---|
|              |            |         | 1HGCG66892A000313 -<br>1HGCG66582A157692  | 8/1/2001 -<br>6/28/2002   |
| Civic 2-Door | 2001       | 09V-259 | 1HGEM22971L000001 -<br>1HGEM229X1L124960  | 9/19/2000 -<br>9/10/2001  |
|              |            | 10V-041 | 1HGEM21931L067826 -<br>1HGEM22561L124788  | 3/19/2001 -<br>9/10/2001  |
|              |            | 11V-260 | 1HGEM22941L005382 -<br>1HGEM21211L125029  | 10/27/2000 -<br>9/10/2001   |
| Civic 2-Door | 2002       | 09V-259 | 1HGEM22902L024786 -<br>1HGEM22932L081872  | 12/6/2001 -<br>5/31/2002  |
|              |            | 10V-041 | 1HGEM21502L000213 -<br>1HGEM219X2L093101  | 9/10/2001 -<br>7/16/2002  |
|              |            | 11V-260 | 1HGEM21392L000001 -<br>1HGEM22532L082887  | 6/5/2001 -<br>6/6/2002  |
| Civic 4-Door | 2001       | 09V-259 | 1HGES15511L000052 -<br>1HGES16551L078249<br>2HGES165X1H500108 -<br>2HGES16571H576787<br>JHMES152X1S000012 -<br>JHMES16551S001089<br>1HGES26701L000002 -<br>1HGES267X1L078061<br>2HGES267X1H500049 -<br>2HGES25741H576724<br>JHMES267X1S000009 ~<br>JHMES26721S005303<br>1HGEN26481 L000004 -<br>1HGEN26401L000742 | 7/18/2000 -<br>8/27/2001<br>8/29/2000 -<br>4/16/2001<br>6/28/2000 ~<br>9/4/2000<br>7/25/2000 -<br>8/27/2001<br>8/28/2000 -<br>4/16/2001<br>7/12/2000 -<br>5/18/2001<br>7/27/2000 ~<br>6/26/2001 |
|              |            | 10V-041 | 2HGES16571H569239 -<br>2HGES16561H576814<br>2HGES26721H542523 -<br>2HGES25791H576718<br>1HGES16581L049070 -<br>1HGES16501L077042<br>1HGES26781L049206 -<br>1HGES26751L077481<br>1HGEN26431L000511 -<br>1HGEN26451L000803  | 3/21/2001 -<br>4/16/2001<br>1/15/2001 -<br>4/16/2001<br>3/22/2001 -<br>8/21/2001<br>3/23/2001 -<br>8/23/2001<br>4/12/2001 -<br>7/26/2001  |

| <b>Make/Model</b> | <b>Model Year</b> | <b>Recall</b> | <b>VIN Range</b>   | <b>Manufacture Date</b>  |
|-------------------|-------------------|---------------|--|--|
|                   |                   |               | JHMES16571S010618 -<br>JHMES16581S012572<br>JHMES26731S005228 -<br>JHMES26711S006300   | 6/1/2001 -<br>7/18/2001<br>6/1/2001 -<br>7/13/2001   |
|                   |                   | 11V-260       | 1HGEN26481L000021 -<br>1HGEN26461L000261<br>1HGES16591L033489 -<br>1HGES16561L078373<br>2HGES16261H514156 -<br>2HGES15561H602491<br>JHMES15221S000019 -<br>JHMES16521S012339<br>1HGES25781L033976 -<br>1HGES26761L078073<br>2HGES267X1H517773 -<br>2HGES25741H603372<br>JHMES26741S000085 -<br>JHMES26781S006231 | 11/15/2000 -<br>12/22/2000<br>10/30/2000 -<br>8/27/2001<br>10/23/2000 -<br>7/9/2001<br>8/1/2000 -<br>7/4/2001<br>10/31/2000 -<br>8/27/2001<br>11/3/2000 -<br>7/11/2001<br>8/2/2000 -<br>7/5/2001 |
| Civic 4-Door      | 2002              | 09V-259       | 1HGES15572L000008 -<br>1HGES15562L057851<br>1HGES25792L000244 -<br>1HGES26782L045822<br>1HGEN265X2L000001 -<br>1HGEN26462L000293<br>JHMES165X2S000067 -<br>JHMES16512S006162<br>JHMES26792S000003 -<br>JHMES26742S003926   | 8/14/2001 -<br>5/22/2002<br>8/28/2001 -<br>4/2/2002<br>6/21/2001 -<br>12/5/2001<br>08/06/2001 -<br>03/07/2002<br>08/28/2001 -<br>02/08/2002  |
|                   |                   | 11V-260       | HGEN26532L000003 -<br>1HGEN26572L000361<br>1HGES16582L000002<br>1HGES16522L044299<br>JHMES16502S000241 -<br>JHMES16552S006150<br>1HGES26772L000001 -<br>1HGES26712L063613<br>2HGES26742H563990<br>JHMES26712S000014 -<br>JHMES26772S003922   | 9/19/2001 -<br>12/12/2001<br>5/24/2001 -<br>3/19/2002<br>8/29/2001 -<br>2/27/2002<br>5/24/2001 -<br>6/14/2002<br>3/20/2002<br>8/30/2001 -<br>2/11/2002   |

| <b>Make/Model</b> | <b>Model Year</b> | <b>Recall</b> | <b>VIN Range</b>   | <b>Manufacture Date</b>                             |
|-------------------|-------------------|---------------|--|---|
| CR-V              | 2002              | 09V-259       | SHSRD684X2U000137 -<br>SHSRD68452U00014  | 10/4/2002 -<br>10/4/2002                            |
|                   |                   |               | SHSRD788X2U000101 -<br>SHSRD78802U000303   | 2/19/2002 -<br>4/11/2002                            |
|                   |                   | 10V-041       | JHLRD68452C000005 -<br>JHLRD68452C020769   | 07/17/2001 -<br>05/31/2002                          |
|                   |                   |               | JHLRD78412C000007 -<br>JHLRO78482C089378   | 05/11/2001 -<br>08/09/2002                          |
|                   |                   | 11V-260       | JHLRD68502C000003 -<br>JHLRD684X2C011534<br>JHLRD78882C000041 -<br>JHLRD788X2C055316 | 6/28/2001 -<br>2/11/2002<br>6/28/2001 -<br>4/4/2002 |
| Odyssey           | 2002              | 10V-041       | 5FNRL18672B000062 -<br>5FNRL187828022371   | 10/9/2001 -<br>5/10/2002                            |
|                   |                   |               | 2HKRL18002H500089 -<br>2HKRL18792H584264   | 7/31/2001 -<br>5/14/2002                            |
|                   |                   | 11V-260       | 2HKRL18602H500002 -<br>2HKRL18652H586536<br>5FNRL186928000001 -<br>2HKRL18992H545109 | 3/6/2001 -<br>6/3/2002<br>8/30/2001 -<br>6/27/2002  |
| Pilot             | 2003              | 10V-941       | 2HKYF185X3H509382  | 6/12/2002   |
|                   |                   | 11V-260       | 2HKYF18153H500005 -<br>2HKYF18603HS15488   | 11/22/2001 -<br>7/17/2002                           |
| Acura 3.2<br>TL   | 2002              | 09V-259       | 19UUA56932A000011 -<br>19UUA56992A046846   | 10/24/2000 -<br>11/2/2001                           |
|                   |                   | 10V-041       | 19UUA56822A005756 -<br>19UUA56772A061652   | 3/19/2001 -<br>1/31/2002                            |
|                   |                   | 11V-260       | 19UUA56992A000031 -<br>19UUA56722A061705   | 12/5/2000 -<br>1/31/2002                            |
| Acura 3.2<br>TL   | 2003              | 10V-041       | 19UUA56623A000069 -<br>19UUA56623A026672   | 2/4/2002 -<br>6/12/2002                             |
|                   |                   | 11V-260       | 19UUA56923A000003-<br>19UUA56823A025927  | 12/4/2001<br>6/7/2002                               |
| Acura CL          | 2003              | 10V-041       | 19UYA41703A006707  | 6/12/2002   |
|                   |                   | 11V-260       | 19UYA41793A000050 -  | 12/4/2001 -   |

| <b>Make/Model</b> | <b>Model Year</b> | <b>Recall</b> | <b>VIN Range</b>  | <b>Manufacture Date</b> |
|-------------------|-------------------|---------------|-------------------|-------------------------|
|                   |                   |               | 19UYA427X3A003330 | 3/19/2002               |